



PW124B

Engine S/N 124492

Engine Details:

Time Since New	7,034
Cycles Since New	10,651
Time Since Overhaul	3,256
Cycles Since Overhaul	5,217
Time Since Hot Section Inspection	0.0

Latest Maintenance Info

Event	Date	Provider
H.S.I. & Repair	March, 2012	AVIO S.p.A.
Overhaul	November, 2007	AVIO S.p.A.

Life Limited Components

Description	Part Number	Serial Number	TCSN	Cycle Life Limit	Cycles Remaining
LP Impeller	3038060	A0025N8D	5,217	15,000	9,783
HP Impeller	3043293	A000LFHH	10,845	15,000	4,155
Cover HPT Front	3039640	42A657	10,651	15,000	4,349
Cover HPT Rear	3039639	A002876T	5,217	15,000	9,783
HTP Disk	3041511	A0027C7N	5,217	15,000	9,783
LPT Disk	3039512	A0027W5K	5,217	15,000	9,783
1st Stage PT Disk	3038513	40A114	10,651	30,000	19,349
2nd Stage PT Disk	3033914	A00285XC	5,217	30,000	24,783
Air Seal Interstage	3039172	TPAA5164	5,217	15,000	9,783
HPT Blades	3115601-01	VARIOUS	5,217	15,000	9,783

Accessories

Description	Part Number	Serial Number
E.E.C.U.	805813-1-005L3	90113044
M.F.C.U.	NOT INSTALLED	
A.F.U.	NOT INSTALLED	
FUEL PUMP	NOT INSTALLED	
FUEL HEATER	10839F	WA4296
IGNITION EXCITER	NOT INSTALLED	
IGNITION EXCITER	NOT INSTALLED	
FLOW DIVIDER	3118512-01	0022
OVERSPEED GOVERNOR	NOT INSTALLED	
OVERSPEED GOVERNOR PUMP	NOT INSTALLED	
WIRING HARNESS	3116993-01	AA3315
OIL COOLER	NOT INSTALLED	
BLEED VALVE	NOT INSTALLED	
SERVOVALVE	NOT INSTALLED	