



PW124B

Engine S/N 124541

Engine Details:

Time Since New	33,637
Cycles Since New	28,288
Time Since Overhaul	0.0
Cycles Since Overhaul	0

Latest Maintenance Info

Event	Date	Provider
Overhaul	August, 2009	Lufthansa AERO

Life Limited Components

Description	Part Number	Serial Number	TCSN	Cycle Life Limit	Cycles Remaining
LP Impeller	3038060	A002EMKF	0	15,000	15,000
HP Impeller	3072766-01	A002M0Y5	0	15,000	15,000
Cover HPT Front	3039640	A002H74P	0	15,000	15,000
Cover HPT Rear	3039639	A002LHT6	0	15,000	15,000
HTP Disk	3041511	A002LRDE	0	15,000	15,000
LPT Disk	3039512	A002HYX0	0	15,000	15,000
1st Stage PT Disk	3038513	A002K969	0	30,000	30,000
2nd Stage PT Disk	3033914	A002KCRF	0	30,000	30,000
Air Seal Interstage	3039172	TPAA9015	0	15,000	15,000
HPT Blades	3115601-01	VARIOUS	0	15,000	15,000

Accessories

Description	Part Number	Serial Number
E.E.C.U.	NOT INSTALLED	
M.F.C.U.	NOT INSTALLED	
A.F.U.	NOT INSTALLED	
FUEL PUMP	NOT INSTALLED	
FUEL HEATER	10839F	WA1586
IGNITION EXCITER	9049400-1	92120286
IGNITION EXCITER	9049400-1	NN92060124
FLOW DIVIDER	3118512-01	2702
OVERSPEED GOVERNOR	NOT INSTALLED	
OVERSPEED GOVERNOR PUMP	NOT INSTALLED	
WIRING HARNESS	3114890-01	9Y754
OIL COOLER	10845B	WA15652
BLEED VALVE	NOT INSTALLED	
SERVOVALVE	NOT INSTALLED	