



BIAero, LLC  
 456 Highway 22 West  
 Whitehouse Station, NJ 08889  
 Ph. 908-534-8350  
 Fx. 908-534-8355

## 2015 PW100 Exchange Pool Pricing

We are pleased to have the opportunity to submit prices for the items listed below.  
 This quotation will remain in effect for 30 days and is subject to current stock availability.

**Note: All cores are due back to BIAero within 20 calendar days after the invoice date. Core PNs must be approved.**

Item No.	Description	Part Number(s)	Quantity	Exchange Price	Core Charge
1	<b>EEC</b> Serviceable Condition Repair not to exceed \$14,000.00	1012974-2-002	1	<a href="#">Quote</a>	<a href="#">Quote</a>
2	<b>Fuel Pump</b> Overhauled Condition Repair not to exceed \$2,400.00	5009982E	1	<a href="#">Quote</a>	<a href="#">Quote</a>
3	<b>Flow Divider</b> Overhauled Condition Repair not to exceed \$850.00	26355-1	1	<a href="#">Quote</a>	<a href="#">Quote</a>
4	<b>TSCU</b> Overhauled Condition Repair not to exceed \$5,000.00	30144-03	1	<a href="#">Quote</a>	<a href="#">Quote</a>
<p><b>Point Of Contact:</b>            Eric Poticny  <a href="mailto:eric.poticny@biaero.com">eric.poticny@biaero.com</a>            908-534-8350</p>					

Name: **Jaime Delia**  
 Title: **Vice President**  
**(908) 534-8350**  
[jaime.delia@biaero.com](mailto:jaime.delia@biaero.com)

Signed: \_\_\_\_\_